BRUHAT BANGALORE MAHANAGARA PALIKE

Engineering Department

COMPLETION REPORT

1	Completion Report of the work of :	**Providing CC camera at Garbage Block spots in ward no -01.**
2	Sanctioned Estimate No. And Date	
3	Name of the Contractor	**KRIDL**
4	Time Stipulated for Completion of work	
5	Date of Commencement	
6	Date of Completion:	
7	Measurment Recorded	
	M.B No	1176
	Page No	117542 to 117552.
8	Name of the Office/ Officials incharge of the work	
	1) Asst. Exe.Engineer	Sri Rajanikanth Mulli
	2) Asst. Engineer	Sri Mallinath M.

Estiamte Amount / Tender	Amount Claimed as per Actuals	Excess	Savings	Rema

1) Certified that the above work has been completed with in the stipulated time Snoted in entrustment.

2) Certified that above work has been executed satisfactorily.

ENGINEER
BRUHAT BANGALORE MAHANAGARA PALIKE

Asst. Executive Engineer
Yelahanka Sub Division
BMP, Yelahanka

ASST. EXE.ENGINEER
SUB - DIVISION
BRUHAT BANGALORE MAHANAGARA
Yelahanka, Bangalore